

As of July 31, 2010, the following USB-Serial (RS-232) adapter cables have been tested and shown to work reliably with the 9000M2 along with PCs on various operating systems. However, results may still be subject to other factors, such as specific PC configuration settings, software conflicts or other unforeseen anomalies. Please contact TOA Product Support if you experience any issues.  
800 733-4748.

<b>9000M2/USB Test Results - Win XP</b>					
<b>Model</b>	<b>9.6K</b>	<b>19.2K</b>	<b>38.4K</b>	<b>57.6K</b>	<b>115.2K</b>
Keyspan USA-19HS	Y	Y	Y	Y	Y
Belken F5U409v1	Y	Y	Y	Y	Y
TrendNet TU-S9	Y	Y	Y	Y	Y
Startech PL-2303	Y	Y	Y	Y	Y

<b>9000M2/USB Test Results – Win Vista</b>					
<b>Model</b>	<b>9.6K</b>	<b>19.2K</b>	<b>38.4K</b>	<b>57.6K</b>	<b>115.2K</b>
Keyspan USA-19HS	Y	Y	Y	Y	Y
Belken F5U409v1	N	N	N	N	N
TrendNet TU-S9	Y	Y	Y	Y	Y
Startech PL-2303	Y	Y	Y	Y	Y

<b>9000M2/USB Test Results – Win 7</b>					
<b>Model</b>	<b>9.6K</b>	<b>19.2K</b>	<b>38.4K</b>	<b>57.6K</b>	<b>115.2K</b>
Keyspan USA-19HS	Y	Y	Y	Y	Y
Belken F5U409v1	N	N	N	N	N
TrendNet TU-S9	Y	Y	Y	Y	Y
Startech PL-2303	Y	Y	Y	Y	Y